AUTHORIZED RELEASE
FAA FORM 8130-3, AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS
FAA/UNITED STATES
4. Organization Name and Address:
Sonnenrich Wood Propeller Co.

SERVICE LETTERS AND MINOR ADJUSTMENTS

WORK	SIGNATURE

N8829
Tach: 622.99

October 2, 2009

Propeller

Removed and reinstalled propeller and serviceable hub after repairs and inspection made by Sensenich Propeller on work orders R033009-2 and G12963.
See AD list for AD compliance.
I certify that this ***Propeller*** has been inspected in accordance with the scope and detail of FAR part 43 appendix d. ***ANNUAL*** inspection criteria and has been found to be in AIRWORTHY condition.
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P-IA

1. Approving National Aviation Authority/Country: FAA / UNITED STATES	2. **AUTHORIZED RELEASE CERTIFICATE** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form tracking Number: 09-0388
4. Organization Name and Address: Sensenich Propeller Service, Inc 1142 Aviation Boulevard, Gainesville, Ga. 30501		5. Work Order/Contract/Invoice Number: G12693

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number	12. Status/Work:
1	Hub Assy.	8808	N/A	1	N/A	Inspected/Tested

13. Remarks: Magnetic Particle Inspection In Accordance with ASTME 1444-93.

14. Certifies the items above were manufactured in conformity to:

☐ Approved design data and are in condition for safe operation.

☐ Non-approved design data specified in Block 13.

19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 13.

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:	16. Approval/Authorization No.	20. Authorized Signature: C. Neal Jones	21. Approval/Certificate No.: S46R346N
17. Name (Typed or Printed):	18. Date (m/d/y):	22. Name (Typed or Printed): C. Neal Jones	23. Date (m/d/y): 6/3/09

USER/INSTALLER RESPONSIBILITIES

It is important to understand the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft can be flown.

FAA Form 8130-3 (6-01) *Installer must cross-check eligibility with applicable technical data. NSN: 0052-00-012-9005

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE

N8829
Tach: 633.9
TSOH 633.9

September 13, 2011

Propeller

Performed 100 hour/annual inspection in accordance with the scope and detail of FAR part 43 appendix d. See AD list for AD compliance.
I certify that this *Propeller* has been inspected in accordance with the scope and detail of FAR part 43 appendix d. ***ANNUAL*** inspection criteria and has been found to be in AIRWORTHY condition.
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P-IA

N8829
Tach: 646.39
TSOH: 646.39

Performed 100 hour/annual inspe
detail of FAR part 43 appendix d
I certify that this *Propeller* has
scope and detail of FAR part 43
criteria and has been found to b
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A

N8829
Tach: ~~657.20~~ 646.39
TSOH: ~~657.20~~

Pro

Performed 100 hour/annual inspect
detail of FAR part 43 appendix d. S
I certify that this *Propeller* has b
scope and detail of FAR part 43 ap
criteria and has been found to be i
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P

SIGNATURE

N8829 October 5, 2012
Tach 646.39
TSOH 646.39

Propeller

Performed 100 hour/annual inspection in accordance with the scope and detail of FAR part 43 appendix d. See AD list for AD compliance.
I certify that this *Propeller* has been inspected in accordance with the scope and detail of FAR part 43 appendix d. ***ANNUAL*** inspection criteria and has been found to be in AIRWORTHY condition.
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P-IA

N8829 February 20, 2014
Tach: ~~657.20~~
TSOH: ~~657.20~~

Propeller

Performed 100 hour/annual inspection in accordance with the scope and detail of FAR part 43 appendix d. See AD list for AD compliance.
I certify that this *Propeller* has been inspected in accordance with the scope and detail of FAR part 43 appendix d. ***ANNUAL*** inspection criteria and has been found to be in AIRWORTHY condition.
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P-IA

OF WORK	SIGNATURE

N8829
Tach: 654.83
TSOH: 654.83

July 12, 2017

Propeller

Performed 100 hour/annual inspection in accordance with the scope and detail of FAR part 43 appendix d. See AD list for AD compliance.
I certify that this ***Propeller*** has been inspected in accordance with the scope and detail of FAR part 43 appendix d. ***ANNUAL*** inspection criteria and has been found to be in AIRWORTHY condition.
Mack Air, LLC Shelbyville, TN
Charles McGaughy 418665781 A&P-IA

		ON OF WORK	SIGNATURE
02 Aug 2018	665.0	INSPECTION for CONDITION CHECK	PROP TO
TSOH	665.0	FLANGE TORQUE - OK	
			399295 9 HP

DATE	TAC