

22AG AIRFRAME VOL 5

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/8/07	Tach 1242.08 TTAF 2899.83			Opened airplane for inspection. Replaced #3 cylinder head temperature probe. Installed new FLT battery and ops checked, next due Sept 2008. Replaced engine baffling P/N 35-910067-7. Complied with AD's 76-07-12, 94-20-04R2 and 72-22-01. All AD's checked and complied with through this date. refer AD compliance Record. I certify that this airplane has been inspected in accordance with an annual inspection and was determined to be in airworthy condition at this time.
				William S. Lynn IA 418155240

FAR 91.411
 WERE
 THIS DATE, AND
 DER
 BY
 ERROR
 T. ALTIMETER READS
 -1545
 -1175
 -680
 -222
 +160
 +700
 +1080
 +1120


or Repair

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
-------	---------------------	----------------	-----------------------	--


Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

06-11-2007 LOG BOOK ENTRY N22AG 1254.4 hrs Work Order 1997

Sent System 60 PSS Programmer, S/N 540A to S-TEC for repair. S-TEC replaced Programmer with S/N 321A on SRO# R52863. Sent PFGC, S/N 2174 for repair. See SRO# R52864. Reinstalled in aircraft.




David Heath
Heath Aviation
FAA CRS HVDR337X



Air Filter P/N 10-23830

Changed at: 1272.4 Hrs. Next Change: 1772.4 Hrs.

Date: 2/29/08 Date: _____



Air Filter P/N 10-23850

Changed at: 1772.4 Hrs. Next Change: _____

Date: 2/29/08 Date: 3/09 Hrs.

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3/2/08	Tach 1272.4 TTAF2930.2			Opened aircraft for annual inspection. Replaced vacuum pressure filter P/N 10-23830 Repco PMA, Vacuum regulator filters 10-23830 Repco PMA, Inspected main & wheel bearing caps P/N 13836 2-629, and cones 13889 2-629, corrected shimming changes w/ MIL-H-5606. Installed new equivalent tailpipe to firewall clamp. Replaced all wing bolts with new in accordance with Beech V35B maintenance manual, section 4, UF NAS152-37, LF 131790-2, UR NAS150-33, LR NAS150-35, NTS 12NB108, 12NB126. Reinspection of torque due at next annual inspection. I certify that this airplane has been inspected in accordance with an annual inspection and has been found to be in airworthy condition at this time. Wilbur S. Jr. FA 3290330

YEAR: DATE
3/2/08
10-19-08

dian or Repair
 worn
 filters
 is
 to
 accordance
 5152-37,
 1NB108,
 section
 accordance
 is
 290330

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>
9/13/08	1282.58			Installed McCauley propeller Hub serial 2A37C223 · C S/N 920256 Blade Blade Model 6-90RD-6 #1 S/N KD165 #2 S/N LE104 is accordance with McCauley Installation instructions, performed operational check no leaks. Villier S. Lynn ATP 3290330
10-19-08				Replaced Narco ELT Battery, ELT FUNCTION TEST Per 91.207(d); BATTERY NEXT DUE 12/2010. GERRY MUSLOV AP 2731840 JA

