

**Textron (Cessna) 340****Airworthiness Directives  
Compliance Report**

<b>Date:</b> 4/29/2024	<b>Tail #:</b> N28913	
<b>Airframe:</b> Textron (Cessna) 340	<b>S/N:</b> 340-0153	<b>Hours:</b> 3592.1
<b>Engine:</b> Continental TSIO-520-NB	<b>S/N:</b> 217744-72K	<b>Hours:</b> 751.8
<b>Engine:</b> Continental TSIO-520-NB	<b>S/N:</b> 217741-72K	<b>Hours:</b> 751.8
<b>Propeller:</b> McCauley 3AF32C515	<b>S/N:</b> 962230	<b>Hours:</b> 751.8
<b>Propeller:</b> McCauley 3AF32C515	<b>S/N:</b> 962270	<b>Hours:</b> 451.8
<b>Misc:</b> hobbs 903.5		

**Airframe: Textron (Cessna) 340**

<b>AD#</b>	<b>Category</b>	<b>Subject</b>	<b>Amdt#</b>	<b>Eff Date</b>	<b>Recurring</b>
74-20-01	Airframe	Main Landing Gear Trunnion	39-1966	09/25/74	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A by serial #		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
76-04-03	Airframe	Autopilot ARC PA-500A Actuators	39-2519	02/26/76	Yes
Date/Hours at Compliance:		Method of Compliance:N/A equipment not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
81-07-11 R1	Airframe	Elevator Balance Weight	39-4096	04/17/81	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A Kit No SK340-24 installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
82-26-05	Airframe	Rudder Balance Weight Rib	39-4519	12/27/82	Yes*
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W by visual inspection of weight rib attachment.		Name:Race Taylor	
Next Due Date/Hours:1003.5		Signature:		Cert#:NONE	
90-02-13	Airframe	Main Landing Gear	39-6445	02/05/90	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A inner bearings replaced by improved bearings.		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
2000-01-16	Airframe	Exhaust System Corrosion	39-11514	02/15/00	Yes
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W sections (b) and (d)		Name:Race Taylor	
Next Due Date/Hours:953.5		Signature:		Cert#:NONE	
2016-17-08	Airframe	Elevator Tab Control System	39-18621	09/12/16	Yes
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W inspection per MEB27-02 1		Name:Race Taylor	
Next Due Date/Hours:1003.5 or 5/25		Signature:		Cert#:NONE	
2023-09-09	Airframe	Exhaust Tailpipe V-Band Coupling	39 22432	07/17/23	Yes
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W with section (k) 1-7		Name:Race Taylor	
Next Due Date/Hours:5/25		Signature:		Cert#:NONE	

**Engine: Continental TSIO-520-NB**

<b>AD#</b>	<b>Category</b>	<b>Subject</b>	<b>Amdt#</b>	<b>Eff Date</b>	<b>Recurring</b>
81-24-06	Engine	Engine Driven Fuel Pump Leaks	39-4260	11/23/81	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A affected pumps not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
86-13-04 R3	Engine	Cylinder Assemblies Pressure Test	39-5850	02/24/88	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A affected cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
97-26-17	Engine	Airmelt Process Crankshafts	39-10260	01/23/98	Yes
Date/Hours at Compliance:		Method of Compliance:C/W at engine overhaul		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
2009-19-07	Engine	EQ3 Cylinder Head Cracks	39-16023	10/07/09	Yes
Date/Hours at Compliance:		Method of Compliance:N/A cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	

2014-05-29	Appliance	SA52000-Axxx, SA55000-A1, and SA55000-A20P - (SAP) Cast Cylinder Assemblies	39-17801	04/25/14	Yes
Date/Hours at Compliance:		Method of Compliance:N/A cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	

**Engine: Continental TSIO-520-NB**

AD#	Category	Subject	Amdt#	Eff Date	Recurring
81-24-06	Engine	Engine Driven Fuel Pump Leaks	39-4260	11/23/81	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A affected pumps not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
86-13-04 R3	Engine	Cylinder Assemblies Pressure Test	39-5850	02/24/88	Yes*
Date/Hours at Compliance:		Method of Compliance:N/A Affected cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
97-26-17	Engine	Airmelt Process Crankshafts	39-10260	01/23/98	Yes
Date/Hours at Compliance:		Method of Compliance:C/W at overhaul		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
2009-19-07	Engine	EQ3 Cylinder Head Cracks	39-16023	10/07/09	Yes
Date/Hours at Compliance:		Method of Compliance:N/A cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	
2014-05-29	Appliance	SA52000-Axxx, SA55000-A1, and SA55000-A20P - (SAP) Cast Cylinder Assemblies	39-17801	04/25/14	Yes
Date/Hours at Compliance:		Method of Compliance:N/A cylinders not installed		Name:Race Taylor	
Next Due Date/Hours:		Signature:		Cert#:NONE	

**Appliance: Cabin Heating & Air Conditioning**

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2017-06-03	Appliance	8xxx and 9xx - Combustion Heater Deterioration	39-18827	05/05/17	Yes
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W section (g) pressure decay test.		Name:Race Taylor	
Next Due Date/Hours:1003.5 or 5/25		Signature:		Cert#:NONE	

**Appliance: Power Plant Turbochargers**

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2023-09-09	Airframe	Exhaust Tailpipe V-Band Coupling	39 22432	07/17/23	Yes
Date/Hours at Compliance:5/6/24@903.5		Method of Compliance:C/W with section (k) 1-7		Name:Race Taylor	
Next Due Date/Hours:1003.5 or 5/25		Signature:		Cert#:NONE	