



Preliminary Invoice

8600 County Rd 32
 Fairhope, Alabama 36532
 United States

July 09, 2021

Telephone: 2519905080

Fax: 2514368680

Bill To: KEVIN GRAVLEY

WO #: AC-10299

Invoice Number: INV21-03370

Item: 1. Beech 58P

Part/Model #: 58P

Item Serial Number:

Registration Number: N6024C

Aircraft Serial Number: TJ185

Discrepancy: 1.1. FUEL SYSTEM SETUP

Resolution: BOTH ENGINES NOTED TO HAVE EXTREMELY LOW FUEL FLOWS/UNMETERED PRESSURES. LH ENGINE INITIALLY NOTED TO MAKE ONLY 2200 RPM. LH ENGINE WAS ADJUSTED WITH NORMAL EFFORTS OF ADJUSTMENTS FROM A FUEL FLOW IN THE UPPER 20'S TO SPEC IN THE MID 30'S. RH ENGINE WILL NOT PRODUCE FLOW WITH UNMETERED PRESSURE WELL ABOVE SPEC. SWAPPED FUEL SERVOS LEFT/RIGHT FOR TROUBLESHOOTING. NO SIGNIFICANT CHANGES IN FLOWS/PRESSURES NOTED LEFT/RIGHT. REPLACED RH ENGINE FLEXIBLE AIR REFERENCE LINES AND REFERENCE LINE SEALS. REINSTALLED SERVOS IN THEIR ORIGINAL POSITIONS. ADDITIONAL MULTIPLE GROUND RUNS PERFORMED. SWAPPED FUEL FLOW TRANSDUCERS LEFT/RIGHT. LOW INDICATION HAD MOVED TO OPPOSITE ENGINE. SUSPECT OBSTRUCTION IN RH FF TRANSDUCER. INSTALLED NEW FF TRANSDUCER IN THE RH POSITION. ADJUSTED THROTTLE AND PROPELLER CABLES AND THROTTLE ARM CLOCKING TO ALIGN HANDLE GEOMETRY. ADJUSTED FUEL PRESSURES LH AND RH. VERIFIED MAGNETO EXTERNAL TIMING TO BE WITHIN SPEC. CLEANED LH ENGINE SPARK PLUGS. MULTIPLE MISFIRING PLUGS NOTED IN TESTER. LH ENGINE SPARK PLUGS HAVE TIGHT GAPS AND APPEAR TO HAVE BEEN SQUEEZED CLOSED. REPLACED LH ENGINE SPARK PLUGS. CLEANED LH FUEL INJECTORS. PERFORMED MULTIPLE GROUND OPS CHECKS AND CHECK FLIGHTS.

	<u>Time & Materials</u>	<u>Flat Rate</u>	<u>Total</u>
Labor:	5,902.00 USD	---	5,902.00 USD
Parts:	3,673.44 USD	---	3,673.44 USD
Misc Charges:	531.00 USD	---	531.00 USD
Total:	10,106.44 USD	0.00 USD	10,106.44 USD

Parts:

<u>Ref. No.</u>	<u>Part number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sell price</u>	<u>Extended</u>
1.1 #1	193-8	Hose 1/2" Reinforced/Ft.	36	0.96 USD	34.56 USD
1.1 #2	193-8	Hose 1/2" Reinforced/Ft.	38	0.96 USD	36.48 USD
1.1 #3	633958-3	Seal - Comp .21 id x .23 thk	12	0.00 USD	0.00 USD
1.1 #4	633958-5	Seal - Comp .34 id x .29 thk	8	0.00 USD	0.00 USD
1.1 #5	102-389012-11	FUEL FLOW TRANSDUCER	1	3,122.40 USD	3,122.40 USD
1.1 #6	RHB32E	Spark Plug	6	40.00 USD	240.00 USD
1.1 #7	RHB32E	Spark Plug	6	40.00 USD	240.00 USD

Miscellaneous

<u>Ref. No.</u>	<u>Miscellaneous Charge</u>	<u>Amount</u>
1.1 #1	FUEL TICKET #16086	94.00 USD
1.1 #2	FUEL TICKET #16200	437.00 USD

Discrepancy: 1.2. OIL PRESSURE LOW.

Resolution: ADJUSTED OIL PRESSURE LH AND RH. MULTIPLE ADJUSTMENTS/GROUND OPS CHECKS REQUIRED.

	<u>Time & Materials</u>	<u>Flat Rate</u>	<u>Total</u>
Labor:	390.00 USD	---	390.00 USD
Total:	390.00 USD	0.00 USD	390.00 USD



Preliminary Invoice

8600 County Rd 32
Fairhope, Alabama 36532
United States

July 09, 2021

Telephone: 2519905080

Fax: 2514368680



Bill To: KEVIN GRAVLEY
5624 CITRUS BLVD
NEW ORLEANS, Louisiana 70123
United States

Invoice Number: INV21-03370
Account Code: 12543
P.O. Number:
Job Number:
Invoice Date: 07/09/2021

Payment Type: Check
Exchange Rate: 1.000000 USD

Payment Terms:

INVOICE SUMMARY FOR WORK ORDER NUMBER: AC-10299

Registration Number: N6024C

	Time & Materials	Flat Rate	Total
Labor:	6,552.00 USD	---	6,552.00 USD
Parts:	3,673.44 USD	---	3,673.44 USD
Misc Charges:	531.00 USD	---	531.00 USD
Total:	10,756.44 USD	0.00 USD	10,756.44 USD
Consumables			161.35 USD
Supplies Haz Waste			10.76 USD
Tax:			307.64 USD
Subtotal:			11,236.19 USD
Total:			11,236.19 USD

Please make checks payable to:

Continental Services
8600 County Road 32
Fairhope, AL 36532

Send wire transfer to:

Continental Services
Regions Bank
11 N. Water Street
Mobile, Alabama 36601
Account Number: 0146569316
ABA Routing Number: 062005690
Swift Code: UPNBUS44