

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J34F-2UF

PROPELLER S/N ED6153B

LOGBOOK # _____

4

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position L.H.

Propeller Model PHC-334F-2UF

Propeller S/N ED6153B

Blade Design FC7391DK

Blade S/N's

No. 1 L40030

No. 2 L40032

No. 3 L40031

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____


Aircraft Model _____

S/N _____

Registration _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

Date	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-30-15	PTTSD 262.6	PHC-J3YF-2UF/FL7391DK S/N	ED 6153B
		PROPELLER CYLINDER REMOVED, PISTON AND ROD FLUSHED FOR POSSIBLE OIL CONTAMINATION. NEW SEALS INSTALLED, CYLINDER REINSTALLED. ANGLES CHECKED. THIS WAS THE ONLY WORK PERFORMED.	
		AUTHORIZED BY	W/B # CR-42264
		<i>[Signature]</i>	
		FOR NEW ENGLAND PROPELLER SERVICE, INC. EAST HADDAM, CT FAA REPAIR STATION # RC2RT130L 1-800-878-6377	

		<h2>L/H PROPELLER MAINTENANCE LOG</h2>			Pro Star Aviation, LLC. Manchester Airport 5 Industrial Drive Londonderry, NH 03053 Repair Station P6UR006Y	
Date: 12/10/2015	W/O: 12957	TTAF: 262.6	Ldgs: N/A	Model: PHC-J3YF-2UF	S/N: ED6153B	N603PG
Hobbs: 262.6	PTT: 262.6					
MAINTENANCE ITEMS: - Removed Left Propeller and reinstalled after repair (flushing) (Ref. New England Propeller Service, Inc. 8130-3 No. 42264 dated 30 Nov 2015) IAW Beechcraft Baron G58 MM 61-10-00. Serviced with Nitrogen IAW Hartzell Owner's Manual.						
The aircraft airframe or appliance identified above was maintained and/or altered and inspected in accordance with current FAA regulations.						
1. Approving Civil Aviation Authority/ Country: FAA/ United States		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 42264	
2. Organization Name and Address: New England Propeller Service, Inc FAA RSN RC2R130L EASA 145.5972		6 Matthews Drive (P.O. Box 244) East Haddam, CT 06423-2388 (860) 873-1494 · Fax: (860) 873-2388			5. Work Order/Contract/Invoice Number: CR- 42264	
7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
HARTZELL PROPELLER	PHC-J3YF-2UF FL 7391DK	1	ED6153B	REPAIRED		
12. Remarks: THIS COMPONENT WAS INSPECTED AND REPAIRED IN ACCORDANCE WITH MANUFACTURER'S MANUAL(S) 117DR16, 2020, V11R51, V6R33, V8R31, V11R35. THE FOLLOWING WORK WAS PERFORMED: PROPELLER CYLINDER REMOVED, PISTON AND ROD FLUSHED FOR POSSIBLE OIL CONTAMINATION. NEW SEALS INSTALLED, CYLINDER REINSTALLED. ANGLES CHECKED. THIS WAS THE ONLY WORK PERFORMED.						

R Date 12/10/2015

