

# 22AG AIRFRAME VOL 4

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
OCTOBER 5, 2004		2245	Tach 1162.9	Removed Left main TIRE SN 40701947 and Replaced with new tire SN 40760315 and new TUBE. Removed Right main TIRE SN 60922005 and replaced with SN 40740335 and new TUBE, cleaned, inspected and repacked wheel bearings. Check gear retraction to check for proper clearance of tires. James Paul Myhl: A4P587053569
10-07-04			Tach 1180.9	weighed A/C on this date as follows: New empty weight 2206 lbs New CG 29.08 New useful load 1124. lbs Ray Cady 68102502 ADD

YEAR:	RECO TACH TIME
DATE	
12/15/04	Tach
	TTA

Technician or Repair

ESTIME  
1005  
checked  
K Fox  
-3569

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12/15/04	Tach 1169.42 TTAF 2327.17			Performed annual inspection. Checked and lubricated all cables and pulleys. Checked landing gear operation and clearance. Checked and serviced brakes and master cylinders as needed. Lubricated all lub points DAV V35 shop manual. Checked all control surfaces and stabilizers. Checked EFT operation and security of attachment. Battery due Sept 06. Complied with AD 72-22-01 by inspection and lubrication of main gear uplock rollers. Complied with AD 94-20-04 R2 by inspecting V-tail structure. Complied with AD 95-04-03 by dye penetrant inspection of front wing spar attachment area. No cracks were found in area. (con't)

**YEAR:** \_\_\_\_\_ **RECORDING TACH TIME** \_\_\_\_\_ **TODAY'S FLIGHT** \_\_\_\_\_ **TOTAL TIME IN SERVICE** \_\_\_\_\_

**Description of Inspections, Tests, Repairs and Alterations**  
 Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

**YEAR:** \_\_\_\_\_ **REC TACH TIME** \_\_\_\_\_

**DATE** \_\_\_\_\_

(Continued from previous page) AD 95-04-03 next due at tach 3327.17.  
 Complied with AD 76-07-12 by confirming proper ignition switch grounding. Replaced r/c aileron pushrod rod end PN HM-4. Tightened throttle control mounts in instrument panel. Replaced engine compartment baffle seal on upper cowling door. Replaced r/c left rear pushrod end on the rudder/rudder pushrod PN AHM4-1006 and checked for proper travel and security of attachment. Replaced induction air filter element Brackett PN BA 7112. Removed disrepair United Instruments PN 300-3BCFL, S/N ~~8935~~ 29431, and artificial horizon 8025-13

(Continued)

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
17	(continued)			P/N 300-3BCFL, S/N 5935 and sent to Rody Aircraft Instruments for overhaul, reinstalled in aircraft. I certify that this airplane has been inspected in accordance with an annual inspection and was determined to be in airworthy condition at this time.
				12/15/04 William D. Lye IA 418155240

ician or Repair  
 doors,  
 the  
 l  
 tachment.  
 settle  
 triments  
 horizon



Technician or Repair

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
12/29/05	Tach 1208.04 TTAF 2865.79			Opened airplane for inspection. Serviced landing gear, brakes and wheel bearings. Complied with AD 76-07-12 by own check. Complied with AD 94-20-0482 by inspection of V-tail structure. Complied with AD 72-72-01 by inspection and fabrication of main landing gear up-lock rod. I certify that this airplane has been inspected in accordance with an annual inspection and was found to be in airworthy condition at this time. ELT checked battery due 9/06. William S. Lynn JA 418155240

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	D E
DATE				

AIRCRAFT LOG ENTRY LABEL

Endorsed with Name, Rating and Certificate Number of Technician or Repair

YEAR:	RECC TACH TIME
2/8/07	Tach
	TT

David Heath  
Owner

Heath Aviation,  
219 Airport Dr.  
Winona Airport  
WINONA, MS. 38967  
662-283-9833

CERTIFIED REPAIR  
STATION NO. HVDR337X  
HA FORM 101

I CERTIFY THAT THE ALTIMETER, ENCODING SYSTEM AND STATIC SYSTEM TEST REQUIRED BY CFR 91.411 HAS BEEN PERFORMED THIS DATE. THE ALTIMETER MAKE, MODEL, & SN United, C106375A, S/N 3209A THE ENCODER MAKE, MODEL, & SN Ameriking, AK350, S/N 34512 WERE TESTED TO 20,000 FT

SIGNATURE *[Signature]* DATE 09/29/06

I CERTIFY THAT THE TRANSPONDER TEST REQUIRED BY CFR 91.413 HAS BEEN PERFORMED THIS DATE AND FOUND TO COMPLY. TRANSPONDER MAKE, MODEL, & SN Apollo, SL70, S/N 6018691

SIGNATURE *[Signature]* DATE 09/29/06

WORK ORDER # 1831