


MADISON AIR CENTER *MAC*
AIRCRAFT SERVICE



BRUCE CAMPBELL FIELD
7450 OLD CANTON ROAD • MADISON, MISSISSIPPI 39110

MARK OCHS
DIRECTOR OF MAINTENANCE

PHONE (601) 853-9358
FAX (601) 853-8305
maintenance@madisonaircenter.net

MCCAULEY™

PROPELLER LOGBOOK

Owner Name _____

Address _____

Propeller Model 2A34C203-C

Blade Model G-90DCA-8

Hub Serial No. 041319

Blade Serial No. 1 YG26303

2 YG26307

3 _____

4 _____

August 26, 2004 Installed factory new McCauley Propeller model: 2A34C203-C
serial number: 041319 on aircraft #N9426C. W/O #27243 -----END-----

Tach Time 758.0

BYAM PROPELLER SER. INC.
4001 N. MAIN HANGER 7 SOUTH
FORT WORTH, TX 76106
FAA REP. STA. WN1R590K
TEL: 817 626-0101

| | | |
|--|--|--|
| | | |
| | | |
| | | |
| | | |

MAINTENANCE & SERVICE HISTORY

| Date | Total Propeller Time | Tech Time Since Overhaul | Description of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|----------|----------------------|--------------------------------|---------------------|---|
| 9-10-05 | 68.1 | 826.1 | Annual Insp C/W | [Signature] AWP1134102JA |
| 10-1-06 | 111.2 | 869.2 | Annual Insp C/W | [Signature] AWP1134102JA |
| 11-18-07 | 182.20 | 940.2 | Annual Insp C/W | [Signature] AWP1134102JA |
| 1-16-09 | 237.50 | 995.5 | Annual Insp C/W | [Signature] AWP1134102JA |
| 5-12-10 | 252.90 | 1010.9 | Annual Insp C/W | [Signature] AWP1134102JA |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Madison Air Center, 7450 Old Canton Rd., Madison, MS, 39110 (601) 853-9358

Propeller Maintenance Entry N9426C July 28, 2012
McCauley 2A34C203-C S/N: 041319 Tach: 1160.7

| |
|------|
| Date |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

Maintenance Actions


- 1) Performed 100 hr/annual inspection/maintenance in accordance with Cessna 100 Series (1953-1962) Service Manual.
 - 2) Performed ground run and operational checks. No defects noted at this time.
- I certify this propeller has been inspected in accordance an **100 HR INSPECTION** in conjunction with an Annual Inspection and was determined to be in an airworthy condition. END.


Ronald D. Thompson A&P 3033312 IA

| |
|--------------------------|
| atures tation pers |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |


Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12


MAINTENANCE & SERVICE HISTORY

Madison Air Center, 7450 Old Canton Rd., Madison, MS, 39110 (601) 853-9358 

Propeller Maintenance Entry N9426C August 8, 2013
 McCauley 2A34C203-C S/N: 041319 Tach: 1242.8

This propeller has been inspected in conjunction with an ANNUAL INSPECTION and is approved for return to service. -END-


 Charles R. Hopper
 AP/IA 3564582

Madison Air Center, 7450 Old Canton Rd., Madison, MS, 39110 (601) 853-9358 

Propeller Maintenance Entry N9426C August 19, 2014
 McCauley 2A34C203-C S/N: 041319 Tach: 1318.7

- Cleaned and dressed Propeller.
 This propeller has been inspected in conjunction with an ANNUAL INSPECTION and is approved for return to service. -END-

Charles R. Hopper
 AP/IA 3564582

| |
|--|
| ed Signatures an and Station ate Numbers |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

MAINTENANCE & SERVICE HISTORY

→ HAWKINS JET CENTER →
 JACKSON, MISSISSIPPI

N9426C Prop. Date 11-03-2015 Tach 1381.8 TT 623.8

C/W Annual inspection on prop. Dressed and painted prop.

Sheldon A Burgess A&P 2159379 IA

Sheldon A Burgess


| Description of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|--|---|
| | |
| | |
| | |
| 1532.4 | |
| NOV 10, 2016 TACH 1532.4 TSO THEY REMOVED PROP DUE | |
| TO DYEF GREASE LEAKAGE @ BLADE ROOTS. | |
| DAVID C. ENTREKIN A&P 378557 | |
| <i>[Signature]</i> | |
| | |

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022
205-426-7022
REPAIR STATION #S6PR302X

PROPELLER DISASSEMBLED, CLEANED & VISUALLY INSPECTED FOR RED DYE
OIL LEAK. REPLACED SEALS & GASKETS, REASSEMBLED & PRESSURE TESTED.
SET ANGLES, TRACKED & BALANCED. PROPELLER REFILLED WITH RED DYE OIL.
THIS WAS THE ONLY WORK PERFORMED.

WORK ORDER # SR-11279
MODEL # 2A34C203C
BLADE MODEL # G-90DCA-8
HUB SERIAL # 041319
DATE: 11/30/2016



JAMES M GAITHER,
GENERAL MANAGER

| | | |
|---|--|--|
| Approving Civil Aviation Authority/Country: FAA United States | AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG | 3. Form Tracking Number: 11279 |
| Organization Name and Address: South Coast Propeller Service, Inc. FAA RSN S6PR302X EASA 145.6306 | 5750 Durose Drive Bessemer, AL 35022 (205) 426-7022 · Fax: (205) 426-7026 | 5. Work Order/Contract/Invoice Number: SR-11279 |

| Item: | 7. Description: | 8. Part Number: | 9. Quantity: | 10. Serial Number: | 11. Status/Work: |
|-------|----------------------|---------------------|--------------|--------------------|------------------|
| | MICHAUD Propeller | 2A34C203C/G-90ACA-B | 1 | 041319 | REPAIRED |

Remarks:
 COMPONENT WAS INSPECTED AND REPAIRED IN ACCORDANCE WITH MANUFACTURER'S MANUAL(S): MPC 200 Rev 2
 FOLLOWING WORK WAS PERFORMED:

PROPELLER DISASSEMBLED, CLEANED AND VISUALLY INSPECTED FOR RED DYE OIL LEAK. REPLACED SEALS AND GASKETS. REASSEMBLED AND PRESSURE TESTED. SET ANGLES, TRACKED AND BALANCED. PROPELLER REFILLED WITH RED DYE OIL. THIS WAS THE ONLY WORK PERFORMED.

| | | | |
|---|----------------------------------|--|--------------------------------|
| <input type="checkbox"/> Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12. | | 14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. | |
| 12. Authorized Signature: | 13c. Approval/Authorization No.: | 14b. Authorized Signature: | 14c. Approval/Certificate No.: |
| | | <i>J M Gaither</i> | S6PR302X |
| 12. Name (Typed or Printed): | 13e. Date (dd/mm/yyyy): | 14d. Name (Typed or Printed): | 14e. Date (dd/mm/yyyy): |
| | | JAMES M GAITHER, G.M. | 30 NOV 2016 |

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft maintenance certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Madison Air Center, 7450 Old Canton Rd., Madison, MS, 39110 (601) 853-9358

Propeller Maintenance Entry N9426C December 1, 2016
McCauley 2A34C203-C S/N: 041319 Tach: 1532.4 TTSN: 774.4

| |
|------|
| Date |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

- 1) Reinstalled propeller after repair by South Coast Propeller Service FAA CRS S6PR302X on work order SR-11279 dated 30 Nov 2016.

This propeller has been inspected in conjunction with an ANNUAL INSPECTION and is approved for return to service. --END--.

Charles R. Hopper
AP/IA 3564582

Madison Air Center, 7450 Old Canton Rd., Madison, MS, 39110 (601) 853-9358

Propeller Maintenance Entry N9426C March 22, 2018
McCauley 2A34C203-C S/N: 041319 Tach: 1642.4 TTSN: 884.4

This propeller has been inspected in conjunction with an ANNUAL INSPECTION and is approved for return to service.

Charles R. Hopper
AP/IA 3564582

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

ures
ation
ers